VLHUB121-MME service note: 100-1 Unstable picture

On a limited range of graphic cards we have seen unstable EDID setting when DIP switched on VLHUB12-MME are is zero setting (factory setting)

Symptom:
Unstable picture in screen

Solution:
Change to DIP switch setting 0100 and reboot VLHUB121-MME

Before

After